



Linx Technologies
159 Ort Lane
Merlin, OR 97532

July 19, 2010

To: All customers using the LC and KH2 Transmitter Module
Re: Product Change Notification

Dear Customer,

Linx Technologies is announcing a change in one of the internal components in it's LC and KH2 Series Transmitters.

Modules assembled with this part meet all published specifications and production test parameters. There is no change in form, fit, markings or part numbers.

We are committed to working closely with our customers regarding this change. Please contact Linx Sales or Customer Service should you have any questions or concerns.

Product Change Notification for the LC and KH2 Transmitter Module

PCN No: LPCN-100611-3

Publish Date: July 19, 2010

Type of Change

Internal component change.

Products Affected

TXM-315-LC_	TXE-315-KH2	CMD-315-HHTX
TXM-418-LC_	TXE-418-KH2	CMD-418-HHTX
TXM-433-LC_	TXE-433-KH2	CMD-433-HHTX

Description of Change

Change of internal part by original part supplier with similar characteristics.

Reason for Change

Supplier inability to meet delivery commitments of historic component.

Effect of Change

Parts meet all published specifications and production test parameters. There is no change in form, fit, markings or part numbers.

The FCC has reviewed the component change and advised that the parts are considered equivalent – no recertification of the end product incorporating the Linx module is required.

Anticipated First Ship Date

Immediate.

Qualification Data

Modules assembled with this part meet all published specifications and production test parameters. There is no change in form, fit, markings or part numbers.

Last Time Buy Date

At this time Linx is unable to supply previous revision product.